

Link do produktu: <https://progsms.pl/fofia-fusera-fuser-film-nie-zawiera-smaru-brother-hl5440-hl5445-hl5450-hl5452-hl5470-hl5472-p-526872.html>

Folia Fusera / Fuser Film (nie zawiera smaru) Brother HL5440, HL5445, HL5450, HL5452, HL5470, HL5472, HL6180, HL6182, (LY5610001)

Cena	102,34 zł
Dostępność	Dostępny
Numer katalogowy	thiFOL-B5440
Kod producenta	FOL-B5440
Kod EAN	5903624350627
Producent	THI

Opis produktu

Folia Fusera / Fuser Film do Brother: Brother HL-5440D, HL-5445D, HL-5450DN, HL-5450DW, HL-5452DN, HL-5470DW, HL-5470DWT, HL-5472DW, HL-5472DWT, HL-6180DW, HL-6180DWT, HL-6182DW, HL-6182DWT Brother DCP-8110D, DCP-8110DN, DCP-8112DN, DCP-8150DN, DCP-8152DN, DCP-8155DN, DCP-8157DN, DCP-8250DN Brother MFC-8510DN, MFC-8512, MFC-8515DW, MFC-8520DN, MFC-8710DW, MFC-8712DW, MFC-8810, MFC-8812, MFC-8910DW, MFC-8912DW, MFC-8950DW, MFC-8950DWT, MFC-8952DW, MFC-8952DWT Brother HL5440D, HL5445D, HL5450DN, HL5450DW, HL5452DN, HL5470DW, HL5470DWT, HL5472DW, HL5472DWT, HL6180DW, HL6180DWT, HL6182DW, HL6182DWT Brother DCP8110D, DCP8110DN, DCP8112DN, DCP8150DN, DCP8152DN, DCP8155DN, DCP8157DN, DCP8250DN Brother MFC8510DN, MFC8512, MFC8515DW, MFC8520DN, MFC8710DW, MFC8712DW, MFC8810, MFC8812, MFC8910DW, MFC8912DW, MFC8950DW, MFC8950DWT, MFC8952DW, MFC8952DWT

- Producent oryginalny: Brother
- Rodzaj: Kolorowa