

Link do produktu: <https://progsim.pl/oryginalna-folia-fusera-fuser-film-oem-nie-zawiera-smaru-hl-l5000-hl-l5100-hl-l5102-hl-l5200-p-550477.html>



Oryginalna Folia Fusera / Fuser Film Oem (nie zawiera smaru) HL-L5000, HL-L5100, HL-L5102, HL-L5200, HL-L5202, HL-L5580, HL-L5585, HL-L5590, HL-L5595

Cena	149,43 zł
Dostępność	Dostępny
Numer katalogowy	thiFOL-B50000
Kod producenta	FOL-B50000
Kod EAN	5903624350481
Producent	OEM

Opis produktu

Folia Fusera / Fuser Film do Brother Brother HL-L5000, HL-L5100, HL-L5102, HL-L5200, HL-L5202, HL-L5580, HL-L5585, HL-L5590, HL-L5595, HL-L6200, HL-L6202, HL-L6250, HL-L6300, HL-L6400, HL-L6402 Brother DCP-L5500, DCP-L5600, DCP-L5650 Brother MFC-L5900, MFC-L5700, MFC-L5800, MFC-L5850, MFC-L6700, MFC-L6750, MFC-L6800, MFC-L6900 Brother HL5000, HL5100, HL5102, HL5200, HL5202, HL5580, HL5585, HL5590, HL5595, HL6200, HL6202, HL6250, HL6300, HL6400, HL6402 Brother DCPL5500, DCPL5600, DCPL5650 Brother MFCL5900, MFCL5700, MFCL5800, MFCL5850, MFCL6700, MFCL6750, MFCL6800, MFCL6900

- Rodzaj: Kolorowa